


Hygro-Thermometer Humidity Alert w/Dew Point



User Programmable Alarms

Warning of High or Low Humidity Conditions

Features:

- Large, easy-to-read triple LCD displays % Relative Humidity, Temperature and Dew Point
- %RH audible and visual alarms, with adjustable set points, alert when humidity exceeds set limit
- Max/Min with Reset function
- Complete with built-in stand, wall mount bracket, and 2 AAA batteries

Applications:

- In summertime, identifies and warns when conditions for mold growth exist
- In wintertime, identifies and warns when low humidity conditions for static electricity exist
- Air temperature and dew point temperature indicate where condensation may occur
- Monitor conditions in laboratories, storage areas and other controlled environment settings



Monitoring Dew Point levels in a Basement for potential mold growth.



Indicates Humidity and Temperature levels in Production areas.



Alerts low Humidity levels in Computer rooms to help prevent electrostatic conditions.



Checks the Humidity and Temperature levels for optimal plant growth in greenhouses.

Specifications	
Humidity	10 to 99%
Temperature	-10 to 60°C (14 to 140°F)
Basic Accuracy	±4%RH; ±1°C/1.8°F
Dimensions	(109 x 99 x 20mm) 4.3 x 3.9 x 0.78"
Weight	169g (6oz)

Ordering Information:

445814Big Digit Indoor/Outdoor Hygro-Thermometer

